







Selection guide

Fuse protection

Application?

Type of operation?

Industry					
					
FUSERBLOC Front/side control 25 to 1250 A <i>p. 134</i>	FUSERBLOC Direct control 25 to 400 A <i>Consult us</i>	FUSOMAT SIDERMAT combination 250 to 1800 A <i>Consult us</i>	RM - RMS 32 to 125 A <i>p. 168</i>	Fuse bases 160 to 2500 A <i>p. 174</i>	gG and AM NFC/DIN 0.16 to 1250 A <i>p. 180</i>

Applications

Transformer output			•			•
Section connectors				•	•	•
Cabinet entrance	•	•	•			•
Wiring						•
Motor circuits	•	•	•			•
Semi-conductor protection				•	•	
Photovoltaic installations						

Device operation

Manual	•	•	•			
Via tripping			•			

Location of manual handle

Front		•	•			
Side		•	up to 1250 A			
Via a panel		up to 32 A				

Location of external handle

Front	•		•			
Right side	•		up to 1250 A			
Left side	Contact us					
Central	Contact us					

Breaking

Fully visible	•	•	•			
Visible			•			

Fuses

NFC/DIN	• / •	• / •	- / •	• / -	- / •	•
BS	see the UK catalogue	see the UK catalogue				•
UL	see UL catalogue	see UL catalogue				•
Other						

