




Replaced by
Remplacer par




Dual dimensions in/mm
Double dimensions in/mm
Doble dimensiones in/mm


"CLIC"





17.5 lb-in
2 Nm



Used for IP65
Utilisé en IP65



Door drilling
Perçage de porte
Perforación de puerta




Used for IP65
Utilisé en IP65


"CLIC"





17.5 lb-in
2 Nm
Pozidriv n°2






Door drilling
Perçage de porte
Perforación de puerta



IF NECESSARY
SI NECESSAIRE



Padlocking the handle
Cadenassage de la poignée
Bloqueable para candados



Defeating the interlock in ON position
Déverrouillage de porte en position I et II
Desenganche del cerrojo en posición I y II

⚠ DANGER / DANGER / PELIGRO

HAZARDOUS VOLTAGE

- Disconnect all power before servicing.
- Be sure enclosure is closed securely before operating device.
- Testing of live equipment should only be performed by qualified service personnel in accordance with local regulations.

Failure to follow these instructions will result in death or serious injury.

TENSION DANGEREUSE

- Couper l'alimentation avant intervention.
- S'assurer de la fermeture du coffret avant manoeuvre de l'appareil.
- Les essais des équipements sous tensions ne doivent être effectués que par du personnel qualifié.

si ces précautions ne sont pas respectées cela entraînera la mort ou des blessures graves.

TENSION PELIGROSA

- Desenergice el equipo antes de una intervención.
- Asegurarse del cierre de la caja antes de manipular el equipo.
- Solamente el personal especializado debiera probar los equipos sobre tensión.

El incumplimiento de estas precauciones podrá causar la muerte o lesiones serias.

